IN THE SPECIFICATION:

Please amend the specification at page 25, line 23, to page 26, line 6, as follows:

The housing part 68 is discontinued in the region of the worm 62, and the gap produced by the toothing engagement between the worm 62 and tooth crown 65 is closed by a roughly cylindrical housing part 87 that surrounds the worm 62. The housing part 87 has only a roughly semicircular shape in the central region of the toothing engagement, whereas on the peripheral ends 88, 89 where the worm 62 is mounted and/or where the drive motor 60 is flanged-on, the cross-section of the housing part 87 roughly corresponds to a complete circle. A lubricant means 88 may be provided in the housing part 87, in particular in the region opposite the toothing engagement. Several, in particular two drive motors 60 and worms 62 as well as housing part 87 surrounding the latter may also be provided in order to increase the drive torque.